

CONNECTING DIAGRAM FOR WIRING FROM CONDENSERS TO OUTGOING TERMINALS AND SHUNT REGULATOR

POWER SUPPLY CUBICLE. H-T AND BIAS CIRCUITS.

FIG. 2.11 (Sheet 3 of 3)